

THIS SERVICE BULLETIN IS FAA APPROVED FOR ENGINEERING DESIGN

SERVICE BULLETIN M20-249
DATE: 1 - 15 - 91

SUBJECT: MOONEY PFM (M20L) IGNITION LEADS, INSPECTION, REMOVAL AND REPLACEMENT;
NOTIFICATION OF PORSCHE SERVICE BULLETIN N/608-028, R1, DATED JUNE 20, 1990.

MODELS/S/N

AFFECTED: MOONEY M20L, PFM, — S/N 26-0001 THRU 26-0041

TIME OF

COMPLIANCE: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN, N/602-028, R1, DATED 6 - 20 -90.

INTRODUCTION: This Mooney Service Bulletin is to advise Mooney Service Centers of an existing Porsche PFM Service Bulletin. REFER TO PORSCHE PFM 3200 SERVICE BULLETIN N/602-028 R1, dated 6-20-90 for action to be accomplished.

INSTRUCTIONS: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN, N/602-028, R1, DATED 6-20-90. Porsche has distributed their Service Bulletin to Service Centers known to have Mooney PFM aircraft in their area. If copies of the Porsche Service Bulletin are required, order PFM SB N/602-028, R1, 6-20-90, from the applicable Porsche Aviation Products, Inc. division address below.

WARRANTY: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN, N/602-028, R1, DATED 6 - 20 -90

REFERENCE

DATA: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN, N/602-028, R1, DATED 6 - 20 -90

PARTS LIST:

In U. S. A. or Canada

Order Porsche Service Bulletin and parts from:

Porsche Aviation Products, Inc.
1600 Holcomb Avenue
Reno, NV, 89520
U. S. A.
Phone: (702) 329-3937
Telefax: (702) 329-0426
Attn: Mr. Gary Butcher

In Europe & rest of the world (except USA & Canada)

Order Porsche Service Bulletin and parts from:

Dr. Ing.h.c.F.Porsche AG
Dept. EMM 3.6
Porschestrasse, P.O. Box 1140
D - 7251 Weissach
Federal Republic of Germany
Phone: 7044-35-2880
Telefax: 7044-35-2902
Telex: 7263763
Attn: Mr. Uwe Sauter

FIGURES/

TABLES: REFER TO PORSCHE PFM 3200 SERVICE BULLETIN, N/602-028, R1, DATED 6 - 20 -90