

This Service Letter reidentified as
Service Bulletin M 20-38
per Service Instruction M20-15.

MOONEY AIRCRAFT, INC.

SERVICE LETTER 20-38

DATE: 8-28-58

SUBJECT: Inspection - Exhaust Stacks

MODELS AFFECTED: M20A Ser. No. 1201 and on

TIME OF COMPLIANCE: At Next Regular 25, 50 or 100 Hour
Inspection and at each 100 Hour
Inspection thereafter

ENCLOSURES: Compliance Card

There have been a few cases reported (on M20A aircraft only) in which the exhaust stacks have cracked around the heater jacket bulkheads and baffles. It is therefore necessary that the heater jacket be removed and that this area of the stacks be carefully inspected for cracks and repaired if necessary. Please complete and return the enclosed compliance card after first inspection.